

New York State Department of Transportation

PIA Safety Flag NB23U4W008

By: Malav Shah

Flag Date: April 20, 2023

Superseding Information:

No Flags Superseded

Structure Information

BIN: 1065318

Feature Carried: 278I278IX2M23027

Feature Crossed: 6TH AVENUE

Orientation: 8 - NORTHWEST

Region: 11 - NEW YORK CITY

County: KINGS

Political Unit: City of NEW YORK

Approximate Year Built: 1962

Posted Load Matches Inventory : Yes

Bridge Load Posting (Tons) : Not Posted for Load

Primary Owner: New York State Department of Transportation

Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party

Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder

This Bridge is not a Ramp

Number of Spans: 322

Verbal Notification Information

Person Notified: Heinz Joachim, P.E.

Date: April 20, 2023 1:00:00 PM

Of: NYSDOT Region 11

Signature Information

Signature: Malav Shah, P.E. 106620-1

Date: April 24, 2023

Reviewed By: Robert Kemp

Date: April 24, 2023

Attachments: 5

Flagged Elements**No Flagged Elements*****Flagged Condition Description***

Location: Span 108, Pier 107, Column C2 end face (50th Street and 3rd Avenue intersection).

Description:

The junction box for the traffic light and attached to Column C2 is broken with exposed electric wires. This location is located at 3' above the ground on the sidewalk and can be accessed by walking. The area is temporarily secured with cones and caution tape.

Flag Photographs

Photo Number: 1

Photo Filename: NB23U4W008 LOCATION PLAN.JPG


**Attachment Description: Safety PIA Flag Location**

Photo Number: 2

Photo Filename: P4202473.JPG



Attachment Description: General view of the flagged condition under Span 108, column C2 at Pier 107. Looking Begin.

Photo Number: 3

Photo Filename: P4202477.JPG



Attachment Description: The sidewalk at the end face of Column 2 of Pier 107 under Span 108. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin.

Photo Number: 4

Photo Filename: P4202475.JPG



Attachment Description: The sidewalk at the end face of Column 2 of Pier 107 under Span 108. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin-Left.

Photo Number: 5

Photo Filename: P4202476.JPG



Attachment Description: The sidewalk at the end face of Column 2 of Pier 107 under Span 108. The electrical junction box is broken with exposed wires. The area has been coned off with yellow caution tape. Looking Begin-Right.